ASPEN $10_{\uparrow}6$ C (F10E) **Draft Questions: Draft Observations:** Is the well venting or 1.) Top of good DPHI/NPHI Gamma 0-1 building pressure in cement bond is at the bradenhead 4930 ft. annulus? 2.) There are no gas shows in the Wasatch formation. Is there a difference between bradenhead 3.) All of the pressures prior to Williams Fork shut-in and post shut-in? formation gas shows being Were there any produced are TDS 800 2,000cement squeezes located above TDS 11000 (depth and date) prior 4930 ft. to or after frac job? 4.) There is TDS 1300 TDS 4800 conflicting Were there any bradenhead 3,000reports of pressure bradenhead pressure information, but prior to fracturing or at times there is any bradenhead pressure pressure build **Top Continuous** monitoring during the up and in some 4,000frac job? cases there is liquid/water flowing at the surface. Top Good Bond 5,000-6,000-